

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 34

Township: 7 North


Range: 1 East

Corner ID: Polk O-25

Monument Description & Remarks: 3" Brass Disk stamped, "T7N R1E, 1/4 S.34, T6N R1E, 1983". Survey Sign 6ft above ground at pt. B. Offset monument to the East was not found

References On File: Kent Anderson survey notes (1983) on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 41 Page No. 70



A - 3" Brass Disk
B - S 86° E 14.84' to Survey
Sign in 17" Sugar Maple
C - S 86° E 19.88' to 3"
Aluminum cap, Lawrenc
County, offset corner
D - S 15° E 44.40' to MAG
nail in 12" Shagbark Hickory
E - N 50° W 37.52' to MAG
nail in 12" Tulip Poplar

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 22nd day of October, 2008.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

Date: 4-7-2009



PO1K-025

Index: Z15

Corner:
S1/4

LAND CORNER RECORD

State of Indiana
Hoosier National
Forest

Twinsp: 7N Range: 1E

Section: 34


2nd P.M.

County: MONROE


EXISTING SURVEYS

Original Government Survey				Original Survey Evidence Found			
Year Surveyed:	1811	By:	Arthur Henrie	Date of Search:		By:	
Original Monument:				Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded:				Year Searched:			
Book: Page: Date:				Monument Found By:			
Monument Set:							
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
Corner is in a ravine and 3' East of the creek bed.	

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.			
South Quarter corner Section 34, T7N R1E; USDA Forest Service monument found in good condition 1.5' above grade. There is a reference monument 20' East of corner, 0.4' above grade.			
Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.		
	8" TULIP, S21°W, 26.9' (PK NAIL IN BASE) 24" MAPLE, N82°E, 14.5' (PK NAIL IN BASE) ALUMINUM MONUMENT, S85°E, 19.7'		
	Corner Recordation:		Certificate Prepared:
	Filed and Recorded in County records:		Date:
	Book:		Page:
Section: 34	Geodetic Coordinates:	Lat./N.	Long./E.
	Edited By:	BRG	Date Created: 11/2007

Index No. 215
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7100-74 (Rev. 5/80)
826-531

T. 7N R. 1E Mer. 2nd N.F. HOOSIER County MONROE State INDIAN A
5 1/4 Corner common to sections 34 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>1984</u> By _____
Where filed or recorded _____	_____
Monument _____ (Original, concrete post, iron rod, etc.)	_____
_____	_____
_____	_____
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

○ Corner F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature Robert J. Stone

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area.

Set A 4' STEEL GALVANIZED CONCRETE FILLED PIPE
3' INTO GROUND WITH A ROCK CAIRN BUILT AROUND IT
MONUMENT SETS ON SOUTH ~~OF~~ POINT OF ISLAND IN
MIDDLE OF STREAMBED. THE FOLLOWING BEARING
TREES AND REFERENCE MONUMENT WAS ESTABLISHED:

TALIP	POPLAR	TALIP	POPLAR	W. OAK	REF. MONUMENT
5"	8"	10"	3' LONG	7" ABOVE GRD.	
S21°W	N53°W	N41°E		EAST	
26.9	37.9'	22.2'		20.0'	

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. Z-15
(Alphabetical - Numerical)

LAND CORNER ⁰ RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 806-924

T. 7N R. 1E 2nd Mer. N.F. Hoosier County Monroe State Ind
5 1/4 Corner common to sections 34 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument wood post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Pogwood W. Oak
Diameter 5" 16"
Bearing S 72 E N 30 W
Distance 12 Ks 26 Ks

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)


Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found



77N R1E Sec 34
Looking Downstream. A Bearing
Tree is in middle of photo
S. 1/4
3/5-*



Sketch

O Corner  F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No ☒

5. Signature _____

Relation of Evidence to Record Features Along Section Lines

Section line to sections 34-3

Object Brook 104MSSE

Record distance E 19 Ch

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: _____

Yes _____ No _____

Filed in county records at _____

Date _____ County Document No. _____

Identified on aerial photo No. _____

Which is filed at _____